

FIG. 1A




FIG. 1B

TN0	TN1	TN2


•
•
•

FIG. Q

TN0 TN1 TN2

Fn=0	Fn=0	Fn=0
Fn=1	Fn=1	Fn=1
Fn=2	Fn=2	Fn=0
Fn=0	Fn=3	Fn=1
Fn=1	Fn=4	Fn=0
Fn=2	Fn=0	Fn=1
Fn=0	Fn=1	Fn=0
Fn=1	Fn=2	Fn=1
Fn=2	Fn=3	Fn=0
Fn=0	Fn=4	Fn=1
Fn=1	Fn=0	Fn=0
Fn=2	Fn=1	Fn=1
Fn=0	Fn=2	Fn=0
Fn=1	Fn=3	Fn=1
Fn=2	Fn=4	Fn=0
Fn=0	Fn=0	Fn=1
Fn=1	Fn=1	Fn=0
Fn=2	Fn=2	Fn=1
....	... 3	... 6

FIG. 3






FIG. 4